

## Instruction manual

# HPS40-1 2+2 female connector with CPA MCC/SCC

2,5mm<sup>2</sup>; 3,0mm<sup>2</sup>; 4,0mm<sup>2</sup>; 5,0mm<sup>2</sup>; 6,0mm<sup>2</sup>



Release August 2022

## INSTRUCTION MANUAL - PLUGGING

### 1<sup>st</sup> step:

Collar the connector [1] to the mating side [2] and insert the connector.



### TIPP:



Consider the correct orientation.

## 2<sup>nd</sup> step:

Insert the connector with force until block.




### TIPP:



If the connector is not at the final position –  
the locking hook stays outside –  
a movement of the CPA (black part) is not possible.

### 3<sup>rd</sup> step:

Move the CPA (black part) to the front block.



#### TIPP:




CPA (black part) is at the final position if the marked part is covered.

## INSTRUCTION MANUAL - DISCONNECT

### 1<sup>st</sup> step:

Pull the CPA (black part) back to the blocking position.



Preferred contact surface


### TIPP:



Pulling back by holding at the marked area on both sides simultaneously.

## 2<sup>nd</sup> step:

First pressing both locking hooks together and then pull the connector.



### TIPP:



Pressing area of locking hook on both sides. If it is easier, it is allowed to support by pulling at the cable.